
VeriFone Omni 3750

The Telephone connection may be located on the bottom of the terminal.



Interconnecting cable part number 6000-6105 REV B.

RDM EC-6014f

The RDM EC-6011f is **NOT** compatible due to no phone connection.

