


VeriFone Omni 3750


The Telephone connection may be located on the bottom of the terminal.



Interconnecting cable part number **07041-00 REV A**.

RDM EC-7014f

The RDM EC-7011f is **NOT** compatible due to no phone connection.



If the merchant is processing Check21, the "Franking Assembly" **MUST NOT** be installed.