

CHECK POS Compatibility Chart

		Check Readers / Imagers										Printers					IMPORTANT NOTES								
		All-in-One POS Solution (Built-in Check Reader/Imager)	EMV Capable	Multi-Merchant Capable	Check 21+ Support (see Above and Imager in GREEN)	Web/Allyn	CRM401	CR600	Ingenico eN2900	Magtek Mini MICR	Magtek Mini/Magtype	CR1000i	RDM 5000/5000A/8000/8000M	Magtek MICR-Image PIN 23410000 for dial Upload & PIN 22410000 for dial Double Side Imager	RDM e7000 Series P250/P200	Scribe 812		Citizen 1000/800/602	Way Systems MIP100 Portable	IP/Ethernet Support	Wireless Support	Integrated Download File (Mag EF Mod. Based For All Processors)	Independent Download File (Mag EF Mod. Based For All Processors)	DL Service Supported (When Integration is Present)	Sage EF Gift Card Support
Point of Sale, Paper Guarantee, & Check 21+																									
ingenico	IVI Checkmanager3000	•																							Unit must have OS version 2.8 or higher and requires printer for Gold/Silver (cannot use I
	AQUA, i5100, i7780		•																						Bronze/Traditional Service req manual Batch "Clear" for proper reporting...No eC5000 Sup
iCT200 and iWL200 Series (Class B)																									
Verifone	Nurit 2080			•																					Possible memory limitations may exist...
	Nurit 2060, 2085, 3000, 3020, 8320			•																					Conflicts between applications/protocols could cause support issues...
	Nurit 2090, 3010, 8000, 8400 (Dial-up & IP Only)			•																					Docking Station required to connect check reader/imager to Nurit 8000...
	Valupak 700, 720 w/Built-in Welch Alllyn Reader	•		•																					
	PC Charge (v5.10.1 and higher)			•																					Supports only the Keyboard Wedge or USB Keyboard Emulator Magtek MiniMICR Reader 22533012)...Franking Devices should be physically removed when processing with the Ch communications (Use "No Modem" model Imagers to lower cost)...
	Omni 3200, 3200SE, 3210																								Stand-alone Check Solution Only...Check app no longer supported in conjunction with B
	Omni 3730 LE, Vx510 LE			•																					Single Application Terminals and WILL NOT Support Credit/Debit or Gift with the Check D require a Imager model with a internal modem)...Only Dial Uploads Supported through the processing with the Check21 Service...
	VX520		8	•																					3730/Vx510 will not support more than TWO Applications...Works w/Bankcard & Check, O GSM/GPRS (Public Access/Open Network SIM)...TNS and Apriva not supported...Image Uj with a internal modem)...Only Dial Uploads Supported through the RDM...Special Image h Wireless Image Uploads)...Franking Devices should be physically removed when process
	Omni 3730, Vx510, Vx570, Vx610			•																					3730/Vx510 will not support more than TWO Applications...Works w/Bankcard & Check, O GSM/GPRS (Public Access/Open Network SIM)...TNS and Apriva not supported...Image Uj with a internal modem)...Only Dial Uploads Supported through the RDM...Special Image h Wireless Image Uploads)...Franking Devices should be physically removed when process
	Omni 3300, 3740, 3750			•																					Requires At least 6 Meg Of Memory For Multiple Add Value Applications...Image Upload h internal modem)...Only Dial Uploads Supported through the RDM...Franking Devices sho Service...
HYPERCOM	T7E (T7E requires a ext. printer)																							** ALL Hypercom's MUST be on FDR (Omaha), TSYS (VITAL), Global (NDC), Paymentech, I	
	T7P, T7Plus, T77			•																					512 K required for T7 (1 meg for Multi-Merchant)...T77 -G(?) models not supported by our
	ICE 5500			•																					1 meg required for ICE (1.5 meg for Multi-Merchant)...
	ICE 5700	•		•																					1 meg required for ICE (1.5 meg for Multi-Merchant)...
	T4100			•																					Checks now handled as Stand-alone application on Multi-app terminals (will work with an Access/Open Network SIM)...TNS and Apriva not supported...Image Upload can be handle model Imagers to lower cost)...Franking Devices should be physically removed when prot
T4200 Series, M4230		8	•																					Checks now handled as Stand-alone application on Multi-app terminals (will work with an Access/Open Network SIM)...TNS and Apriva not supported...Image Upload can be handle model Imagers to lower cost)...Franking Devices should be physically removed when proc	
RDM	RDM Synergy I	•		•																					Franking Device must be physically removed when processing with the Check21 Service...
	RDM Synergy II	•		•																					Support is handled by Commerçant...
Commerçant	Mobilescape 5000 (Class B)	•		•																				Support is handled by EMS...	
axalto	Axalto Magic 6100 (Class B)																							Support is handled by EMS...	
TechTrex Inc.	PrimeTrex One	•	8	•																				Auto-Close does not work properly in Multi-App mode...No eC5000 Support...Image Uploa "No Modem" model Imagers to lower cost)...Franking Devices should be physically remov	
	PrimeTrex IP/PrimeTrex S		8	•																					Only RS232 versions of the Magtek Mini MICR are currently supported (no USB)...eC7 RDI the Terminal communications (Use "No Modem" model Imagers to lower cost)...Requires Devices should be physically removed when processing with the Check21 Service...No CF Settlement ONLY...
Heartland	Dejavoo X, M, Vega and Vega S Lines		8	•																				Support is handled by Heartland...Supports only the hardware revision "M" and later on t Imager (will require a Imager model with a internal modem)...	
	Heartland e3 (Class B)																								Support is handled by Heartland...Supports only the hardware revision "M" and later on t Imager (will require a Imager model with a internal modem)...
PAX	PAX S90, S90, SP30, MT30, S300, S500, S800, S900, D200, and D210 (Class B)		•																						For more information contact PAX Technology at (904) 900-3741, or visit their website at w

Bronze & Paper Guarantee Only

LinkPoint	LinkPoint 2000, 3000/AIO																								FDR Only, and no reader capability on the Linkpoints...Applications do not support Card
	Zon Jr, XL300, Tranz 330, & T380																								See notes below...
Verifone	Tranz 380x2			•																					Multi-Merchant limited to 2 (with both sides loaded for checks only)...
	Tranz 420 & Tranz 460																								See notes below...
	8020 (Supports Dial-up only on Checks)			•																					No Reader support on Docking Station for 8020...
CHARGE Anywhere	Comstar/Charge Anywhere 3010 and 8000 (Class B)																								
	EncomPOS Software (Class B)																								Setup and Support is handled by EncomPOS...
Way Systems	Way 5000 (Class B)																							Setup and Support is handled by Way Systems...For more information contact Way System www.WaySystems.com...	

Please refer to the Gateway Sheet for additional compatibility on Gateway products!

- 1 = Check reader support available w/ "Standalone" check service only. If using both credit and check on the terminal, MICR information must be manually entered.
- 2 = Full MICR program available w/Check Only service on 2nd side of terminal, otherwise refer to rule 1.
- 3 = Supported only in certain applications. Please call Technical Support for details.
- 4 = Configuration Check(s) are required for this check reader/imager.
- 5 = This Reader must be mailed into Technical Support to be configured.
- 6 = Supports only the USB keyboard emulator or keyboard wedge model Magteks.
- 7 = Requires the eC7014 or eC7014F model Imager connected to a phone line.
- 8 = EMV Capable indicates that the Hardware is capable of supporting EMV. Consult with your processor to determine if software for this terminal is available for an EMV solution.

*** Be advised that we are unable to incorporate our Value Added Services into certain Class A applications/Processors ***
(Please feel free to call Technical Support at 1-877-438-3249 for details/limitations)